

No. of Radial spacers = 40
 No. of Strips = 40

Pos.212




Bild.N.01

Windings Internal Connection (Right screw)

36




Bild.N.02

Windings External Connection-Back (Right screw)

35




Bild.N.03

Windings External Connection (Right screw)

34,35





Bild.N.04

cross out tripel conductor



| | |
|-------|-----------|
| DRAWN | 1/22/2023 |
| CHECK | 1/22/2023 |

GLOBAL LEADER

OS-winding

DWG OS-N20
 SHAT AL BASRA POWER PLANT